

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interception ID: 10027850	terrestien ID: 40027050 Main Street, SUADON DD					NI/A	Location			
Intersection ID: 10037850	Main Street: SHARON_RD			Cross Street: N/A					Location:	NW
ADA ID: AC092A59BD18	BD18 Ramp Type: MedianPerp			Initial Pass/Fail: Fail Overall Compliance: No					Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	Black	Possible Solutions:		Compliance Description Data Co			Comp	Compliance Description Data		
and the second of the		Remove & Replace E	ntire Ramp.	I	N/A	Ramp Length (in)	58.0	Yes	Ramp Slope (%)	6.0
	al"		•	I	No	Ramp Width (in)	44.0	No	Ramp XSlope (%)	2.9
a com ne	TP P			I	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	ak 1			I	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
and the second	FI IT W			I	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the second				I	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		I	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Barris Carlos Ca		N/A		I	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	11 . 61=	4		I	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Le Cate		7		I	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
an ant the	11			I	N/A	Shared Landing?	N/A			
as when and a fi	S 1 5 1	PROW/ADA:		I	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
🗙 🚥 – 📭 🔰 📲 🗍 //	The second	Not Found, R304.5.1,	R304.5.3	I	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
P 105 60				I	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
		ł				X Walk 1 Direction	To N		X Walk 2 Direction	N/A
	Mallow			I	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE					X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	1.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			I	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 10	650.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

