

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Good

Surface Condition? (G/P)

Intersection ID: 10829 Main Street: E_34TH_ST Cross Street: HOLT_ST Location: N

ADA ID: AD50AAC39758 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name E 34TH ST
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:						
Remove & Replace Entire Ramp.						
	١					
Surveyor Notes:						
N/A						
PROW/ADA:						
Not Found, R304.5.1, R304.2.2						

Total Cost: \$

	r leid Measurements/Component Compnance								
Compliance Description		Data	Compliance Description		Data				
	N/A	Ramp Length (in)	55.0	No	Ramp Slope (%)	11.2			
	No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	2.0			
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
	N/A	Shared Landing?	N/A						
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A			
		X Walk 1 Direction	To SW		X Walk 2 Direction	N/A			
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A			
		X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	N/A			
		X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	N/A			
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A			
		Road Slope (%)	N/A	N/A	Clear Space?	N/A			
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
		Obstruction Type			Storm Grate/Utility Type				







1850.00