

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Street: MICROSOFT_WY			Cross	Street:	HANSON_RD	Location:	NW			
ADA ID: AD6C1842A35A	Ramp Type: Directional1			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	X	Possible Solutions:			Compliance Description			Data Compliance Description			
· Colores and ·		Remove & Replace Entire	Ran	np.	N/A	Ramp Length (in)	60.0	N/A	Grade Break?	N/A	
					No	Ramp Width (in)	47.0	N/A	Grade Break Slope (%)	0.0	
Contraction of the second s					Yes	Ramp Slope (%)	5.4	N/A	Grade Break XSlope (%)	0.0	
· · · · · · ·					No	Ramp XSlope (%)	2.1				
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
		Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		DWS LCOATED ON LNDG	i		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
A A A A A A A A A A A A A A A A A A A					N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
S DIGE				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A		
6	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A		
	R304.5.1, R304.5.3			N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
6 / B		· · · · · · · · · · · · · · · · · · ·			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
					N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
	8			N/A	Painted X Walk1?	No		Road Slope (%)	0.9		
Street 1 Name	HANSON RD					X Walk 1 Direction	To SW		Road X Slope (%)	2.4	
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A					X Walk 1 Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	2.4	N/A	Storm Grate/Utility Hazard?	N/A	
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
					N/A	Any Obstructions?	N/A			N/A	
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
							N/A	N/A	Curb Slope (%)	3.0	

