

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25211Main Street:SMITH\_RDCross Street:SOUTHBRIDGE\_FOREST\_DRLocation:SEADA ID: ADAB08BA14C1Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:13.75

**Codes/Mitigation Info/Possible Solution** 



A TANANCE STATE OF THE PARTY OF	CONTRACTOR OF THE PROPERTY OF
Street 1 Name	SMITH RD
Stop Condition-Street	2 None
Street 2 Name	N/A
Stop Condition-Street	1 N/A

i	Fussible Solutions.	
į	Remove & Replace Entire Ramp.	N
		Y
4		N
1		N
No. of Lot		N
		N
1	Surveyor Notes:	N
	N/A	N
		N
1000		N
1		N
1	PROW/ADA:	N
Sept. In	Not Found, R304.2.2, R304.5.3	N
		N
		N
		N

OWNER



Total Cost:



1850.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	119.0	No	Ramp Slope (%)	10.2			
Yes	Ramp Width (in)	85.0	No	Ramp XSlope (%)	2.6			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			