

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 54366	Main Street: CADEN_RD			Cross Street: COLLINS_FORD_RD				Location:	NW	
ADA ID: AE7CD6E94B32	Ramp Type: BlendTrans1			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Comp	Compliance Description Data			Compliance Description		
		Remove & Replace Curb Two New Directional Ran Equivalent.	Ramp With	N/A	Ramp Length (in)	180.0	Yes	BlendTrans Slope (%)	2.9	
			•	Yes	Ramp Width (in)	99.0	No	BlendTrans XSlope (%)	5.7	
			•	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
Ga				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
- Con		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
ی <mark>با با</mark> م	8 A A	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
PROW/ADA:			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
			N/A	Shared Landing?	N/A					
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
and the second second second second	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
1 1 1 1 1 1 S				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A		
				X Walk 1 Width (in)	98.0		X Walk 2 Width (in)	N/A		
Street 1 Name	COLLINS FORD RD	-			X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A				Road Slope (%)	2.4		Clear Space?	N/A	
					Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$ 3200.0	)	Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

8.0