

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

3.7

8.5

N/A

N/A

N/A

N/A

N/A

Intersection ID: 13177 Main Street: BETHEL RD **Cross Street: CARTIER WY** Location: W **ADA ID: AED80FDE56CA** 

**Overall Compliance: No** Ramp Type: BlendTrans2 Initial Pass/Fail: Fail Severity Score: 33.75

N/A

No

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Flare Traversable LT?

Flare Type LT

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance

Yes

No

N/A

N/A

N/A

N/A

N/A

Compliance Description

Flare Type RT

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

Flare Traversable RT?

BlendTrans Slope (%)

BlendTrans XSlope (%)

Data

84.0

45.5

N/A

N/A

N/A

N/A

N/A



**BETHAL RD** Street 1 Name Stop Condition-Street 1 None N/A Street 2 Name Stop Condition-Street 2 N/A Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3 Total Cost:

|           | V |         |    |
|-----------|---|---------|----|
| Section 1 | 4 | Sign of |    |
| ****      |   |         |    |
|           | 7 | 7       | 1  |
|           |   |         | MA |

N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To NE X Walk 2 Direction N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 7.8 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 6.4 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? N/A Road Slope (%) 6.4 Clear Space? N/A Road X Slope (%) 7.8 N/A Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A 3200.00 Obstruction Type Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good No Curb Slope (%) 13.3



