

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

91.0

42.0

5.0

14.4

7.2

4.3

N/A

Cross Street: CASA LYNDA LN Intersection ID: 8785 Main Street: HOOD RD Location: NE Initial Pass/Fail: Fail **Overall Compliance: No** 25 ADA ID: AF65FC07DE4B Ramp Type: Combination2 **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

No

Yes

No

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

N/A

N/A

N/A

N/A

60.0

63.0

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name StopSign Stop Condition-Street 1 CASA LYNDA LN Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. N/A N/A N/A N/A Yes Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1, R304.5.3 N/A N/A N/A N/A N/A





Total Cost:



	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
		X Walk 1 Direction	To S		X Walk 2 Direction	N/A
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	7.8		X Walk 2 X Slope (%)	N/A
1600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A		Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
3 S. A. C.	0			N/A	Any Obstruction?	N/A
		The state of the s			Obstruction Type	
4	1					N/A
	1			N/A	Storm Grate/Utility Hazard?	N/A
1-11-					Storm Grate/Utility Type	
						N/A
				Yes	Surface Condition? (G/P)	Good
1					Curb Slope (%)	58.0
7 3 4						