

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44267 Main Street: BRITTNI_DAYLE_DR Cross Street: ISAAC_HUNTER_DR Location: NE

ADA ID: AF71EA44BA35 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

BRITTNI DAYLE DR StopSign ISAAC HUNTER DR None

Possible Solution							
Possible Solutions:							
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.							
Surveyor Notes:							
Surveyor Notes.							
N/A							
PROW/ADA:							
Not Found, R304.5.1, R304.5.3							

Total Cost: \$ 3200.00

	Field Measure	ements/C	ompo	nent Compliance		
Compliance Description		Data	Compliance Description		Data	
N/A	Ramp Length (in)	42.5	Yes	BlendTrans Slope (%)	2.8	
No	Ramp Width (in)	47.0	No	BlendTrans XSlope (%)	5.5	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	X Walk 1 Direction	To W		X Walk 2 Direction	To S	
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	4.7	
	X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	1.3	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	6.4		Clear Space?	N/A	
	Road X Slope (%)	3.6	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	
			No	Curb Slope (%)	7.0	





