

Access Compliance Report Public Rights-of-Way (Curb Ramps)



										—— I	
Intersection ID: 21220	Main Street: MANOR_MILL_RD			Cross	Cross Street: SHARON_VIEW_RD				Location:	NE	
ADA ID: AF7B0234C80D	Ramp Type: Directional2			Initial	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	10		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	Striken .	Possible Solutions:		Compliance Description			Data Compliance Description				
	A.	Remove & Replace Entil	re Ran	מו.	N/A	Ramp Length (in)	58.0	N/A	Grade Break?	N/A	
	E/st				No	Ramp Width (in)	46.0	N/A	Grade Break Slope (%)	0.0	
					Yes	Ramp Slope (%)	1.6	N/A	Grade Break XSlope (%)	0.0	
TO BE REAL	A LAND	2			No	Ramp XSlope (%)	2.7				
8/10/2	· > /2	9			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
S S S S S S S S S S S S S S S S S S S	- K.				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
6	55 8 3	Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
Star to	1000 1 An	N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
Non Market	a in a				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
					N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	et ph				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
		PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	200	R304.5.1, R304.5.3			N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	and a				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	The				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
		1			N/A	Painted X Walk1?	No		Road Slope (%)	3.2	
Street 1 Name MANC	R MILL RD	-				X Walk 1 Direction	To W		Road X Slope (%)	0.4	
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A					X Walk 1 Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	0.4	N/A	Storm Grate/Utility Hazard?	N/A	
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
					N/A	Any Obstructions?	N/A			N/A	
		Total Cost:	\$	1800.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
							N/A	N/A	Curb Slope (%)	1.8	





