

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2789 Main St	Main Street: MARSHBANK_LN			RIDGEFIELD_DR	Location:	SW		
ADA ID: B0CC78015E7B Ramp 1	E7B Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	58.75
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
Possible Solutions:			Compliance Description Dat			a Compliance Description Data		
12 12 Torrent Maria	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	13.1
			No	Ramp Width (in)	38.0	No	Ramp XSlope (%)	7.5
		1	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		1	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
THE PARTY IN COMPANY	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
The B	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		1	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
2 A Plantin P		1	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
AN A NO PATIENS	5×	1	N/A	Shared Landing?	N/A			
And the second states	PROW/ADA:	1	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2,		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	R304.5.3	1	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
TOTAL CARACTER AND A SECOND				X Walk 1 Direction	To N		X Walk 2 Direction	N/A
- State and the second		1	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name MARSHBANK LN	-			X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	850.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

es Surface Condition? (G/P)

Good

