cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15287	Main St	Main Street: ALBEMARLE_RD			treet:	N_SHARON_AMITY_R	Location:	NW		
ADA ID: B15A0A2B1725	Ramp T	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
Possible Solutions:							liance Description	Data		
	8	Remove & Replace Entire Ram			N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	7.2
		Remove & Replace	nure kamp.		No	Ramp Width (in)		No	Ramp XSlope (%)	2.2
					N/A	Flare Type LT	47.0 N/A	N/A	Flare Type RT	2.2 N/A
	E E	*			N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A N/A
	A A A					,			,	
	DIL AV	-			N/A	Flare Traversable LT?	N/A	N/A N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A		DWS Provided?	N/A
the second second		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
6		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
ALL		5			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
TENASS.					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Aller A	TILL"				N/A	Shared Landing?	N/A			
L. C.	TUIL	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
1 100 12	ALL AMARTINA	Not Found, R304.5.1	, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
120 0	1 88 A P				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
6	111 4					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
S. A.				N/A	X Walk 1 Width (in)	113.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	ALBEMARLE RD					X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
1			·			21	N/A			N/A
								1		

Yes Surface Condition? (G/P)

Good





