cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25150	Main Street:	Cross Street: WINBURN LN					Location:	w	
ADA ID: B216CE1A630D		Initial Pass/Fail: Fail Overall Compliance: No						33.75	
· · · ·									33.75
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
1 1 Martin and the second	Poss	sible Solutions:	Compliance Description		Data Compliance Description		liance Description	Data	
	Re	emove & Replace Entire Ramp	. N//	Α	Ramp Length (in)	64.0	No	Ramp Slope (%)	12.3
and the second second	1 200		No	D	Ramp Width (in)	45.0	Yes	Ramp XSlope (%)	1.3
	1 -		N//	Α	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A A A A A A A A A A A A A A A A A A A			N/2	Α	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Con the second	Shields.		N/2	Α	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A A A A A A A A A A A A A A A A A A A	The second		N//	Α	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
S. A. S. S.	Surv	veyor Notes:	N//	Α	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
6 SX	N/	Ά	N//	Α	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/2	Ά	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second se	-		N/2	Α	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Survey and the second sec	The w		N//	Α	Shared Landing?	N/A			
	PRO	DW/ADA:	N/2	Α	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A I T	No	ot Found, R304.5.1, R304.2.2	N//	A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	the second second		N//	Α	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
a start and the	200				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
a hard a second hard hard hard			N/2	Α	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name WIN	NBURN LN				X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N//	Α	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/	A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total	al Cost: \$	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A		, ,,,	N/A





Yes

Surface Condition? (G/P)

Good