

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-							
Intersection ID: 18605	Main Street: MOCKINGBIRD_LN			Cross Street: PARK_RD				Location:	NW
ADA ID: B25F18BE89CC	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	THE REAL PROPERTY.	Possible Solutions:		Compliance Description			Data Compliance Description		
A particular of the particular		Remove & Replace Entire F	Ramp.	N/A	Ramp Length	(in) <b>66.0</b>	N/A	Grade Break?	N/A
		·····		Yes	Ramp Width (i	n) <b>76.0</b>	N/A	Grade Break Slope (%)	0.0
				No	Ramp Slope (%	%) 10.8	N/A	Grade Break XSlope (%)	0.0
A STATISTICS				No	Ramp XSlope	(%) 3.6			
	R			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT	r (%) N/A	N/A	Flare Slope RT (%)	0.0
MOCEKINGEIRD LIN		Surveyor Notes:		N/A	Flare Traversa	ble LT? N/A	N/A	Flare Traversable RT?	N/A
		N/A		N/A	Landing Lengt	h (in) 0.0	N/A	DWS Provided?	N/A
				N/A	Landing Width	(in) <b>0.0</b>	N/A	DWS Contrast?	N/A
the second terms	-Warman			N/A	Landing Slope	(%) 0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slop	pe (%) 0.0	N/A	DWS Full Width?	N/A
	F	PROW/ADA:		N/A	Landing Curb?	P (Y/N) N/A	N/A	DWS Offset LT (in)	N/A
RELIN	1 1	R304.2.2, R304.5.3		N/A	Shared Landin	ig? N/A	N/A	DWS Offset RT (in)	N/A
		····, ····		N/A	Gutter Ponding	g? <b>0.0</b>	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (i	in) <b>0.0</b>	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Wall	k1? No		Road Slope (%)	1.5
Street 1 Name	OCKINGBIRD LN				X Walk 1 Direc	tion To SE		Road X Slope (%)	1.3
Stop Condition-Street 1	StopSign				X Walk 1 Width	h (in) N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope	e (%) 1.5	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slo	ope (%) 1.3	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside X	Walk1? N/A		Storm Grate/Utility Type	
				N/A	Any Obstructio	ons? N/A			N/A
		Total Cost:	\$ 160	00.00	Obstruction Ty	pe	Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	8.5

