

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

46.0

60.0

7.1

1.7

5.2

1.3

N/A

Intersection ID: 53960 Main Street: DENBUR DR **Cross Street: MAGNOLIA LILY AV** Location: S Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: B409E894AD25 Ramp Type: Combination2 **Severity Score:** 8.75

**Codes/Mitigation Info/Possible Solution** 

## **Field Measurements/Component Compliance**

N/A

Yes

Yes

Yes

Yes

Yes

N/A

No N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

61.0

59.0

1.4

0.6

48.5

47.5

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name None **DENBUR DR** Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. N/A N/A N/A N/A No Surveyor Notes: N/A LT RP < 5% N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1 N/A N/A N/A N/A N/A N/A

\$





Total Cost:



	11//	r antica / Walkir:		17/7	I dilitod / Walkz:	14/74
		X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A
1600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A		Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstruction?	N/A
	,-				Obstruction Type	
						N/A
				N/A	Storm Grate/Utility Hazard?	N/A
		TO THE STATE OF TH		l	Storm Grate/Utility Type	14/74
All and a second	1					N/A
				Yes	Surface Condition? (G/P)	Good
					Curb Slope (%)	14.0
	2					