cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 43273	tersection ID: 43273 Main Street: OLD_PROVIDENCE_RD			Cross Street: RED_BIRD_TL				Location:	Ν
ADA ID: B48CC09F4422	D: B48CC09F4422 Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	HOWER -	Possible Solutions:						ompliance Description Data	
		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	108.0	No	Ramp Slope (%)	9.2
V La State State		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.7
5.				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	· · · · · · · · · · · · · · · · · · ·			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Q	a participation	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	BIRD TIL	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
No. 10 10 10				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the transfer of the second secon				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Part War	¥20 1			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
and for the second		Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	all Maria			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
FILL A SEC.					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
1 Car Angela	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	OLD PROVIDENCE RD				X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	0.6
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	1.7
Street 2 Name	RED BIRD TL			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.9	N/A	Clear Space?	N/A
					Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

