

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31447 Main Street: RIDING_HILL_AV Cross Street: GLENLUCE_AV Location: N

ADA ID: B52D627CF5DD Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33.75

Codes/Mitigation Info/Possible Solution



Street 1 Name RIDING HILL AV
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:				
Remove & Replace Entire Ramp.				
	ı			
Surveyor Notes:				
N/A	ı			
	ı			
	ı			
PROW/ADA:				
Not Found, R304.5.1, R304.5.3	,			
	,			
	ı			
	ı			





Total Cost:



1850.00

				•			
Field Measurements/Component Compliance							
Comp	Compliance Description Data		Compliance Description		Data		
N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.4		
No	Ramp Width (in)	45.5	No	Ramp XSlope (%)	7.8		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	6.4		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type		l	Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		