

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.0

8.3

N/A

Intersection ID: 31459 Main Street: BOBTERRY CT Cross Street: BOMAR DR Location: NE **Overall Compliance: No** ADA ID: B5C536FCE55B Ramp Type: PerpDiag Initial Pass/Fail: Fail Severity Score: 33.75

Compliance Description

N/A

No

N/A

Ramp Length (in)

Ramp Width (in)

Flare Type LT

Codes/Mitigation Info/Possible Solution

Possible Solutions:

Field Measurements/Component Compliance

47.5 No

Yes

N/A

54.5

N/A

Data Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Type RT



Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.



					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	The contract of				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	THE!				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Bonds		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
WAR DO	3				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
ė.					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
A PART PART	4	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R	304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
11 器 章 器		,	·		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
AFT THE STATE OF	Maria Res					X Walk 1 Direction	To W		X Walk 2 Direction	To S
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name	BOB TERRY CT					X Walk 1 Slope (%)	9.2		X Walk 2 Slope (%)	0.1
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	7.4
Street 2 Name	BOMAR DR				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None					Road Slope (%)	4.2	N/A	Clear Space?	N/A
						Road X Slope (%)	7.9	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type		l	Storm Grate/Utility Type	
							N/A			N/A
								Yes	Surface Condition? (G/P)	Good
HHI										