cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10488	Main Street: ASHWOOD_DR			Cross	s Street:	CHESTNUT_RIDGE	Location:	NW			
ADA ID: B6115F17BA68	Ramp Type: BlendTrans1			Initial	Pass/Fa	ail: Fail Overal	o Severity Score:	10			
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description			Data Compliance Description			
		Remove & Replace Curb Ra Two New Directional Ramps Equivalent.	Ram	n With	N/A	Ramp Length (in)	90.0		BlendTrans Slope (%)	2.0	
				•	No	Ramp Width (in)	47.5	No	BlendTrans XSlope (%)	2.8	
A state of the sta					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A	
					N/A	Landing Length (in)		N/A	DWS Provided?	N/A	
		Surveyor Notes:			N/A	Landing Width (in)	N/A		DWS Contrast?	N/A	
		NO LT SW			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
CHESTNUT_RIDGE_DR					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	0				N/A	Shared Landing?	N/A				
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
In the second second		Not Found, R304.5.1, R30	04 5 4	2	N/A	Gutter Lip Ht (in)		N/A	Gutter X Slope (%)	N/A	
		U 4 .J.	5	N/A	Painted X Walk1?		N/A	Painted X Walk2?	No		
					X Walk 1 Direction	To S		X Walk 2 Direction	To E		
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A		
Street 1 Name	CHESTNUT RIDGE DR	2				X Walk 1 Slope (%)	N/A		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	N/A		X Walk 2 X Slope (%)	N/A	
Street 2 Name	ASHWOOD DR				N/A	Ramp inside XWalk1?		N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	StopSign					Road Slope (%)	3.3		Clear Space?	N/A	
						Road X Slope (%)		N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type		
			+				N/A			N/A	
								1			







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.9