

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

10.2

Intersection ID: 6370	Main Street: LAKE_RD			Street:	MILHAVEN_LN	Location:	NW		
ADA ID: B77470489B4B	Ramp Type: Para			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Complian			liance Description	Data	
		Remove & Replace Entire Ran	מו.	N/A	Ramp Length LT (in)	60.0	N/A	Ramp Length RT (in)	55.0
			.6.	Yes	Ramp Width LT (in)	58.0	Yes	Ramp Width RT (in)	58.5
	T			Yes	Ramp Slope LT (%)	3.3	No	Ramp Slope RT (%)	11.1
	1 III Total			Yes	Ramp XSlope LT (%)	1.4	Yes	Ramp XSlope RT (%)	1.5
	B			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
- 12 12				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1	Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
E.	E	LT RP < 5%		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	ta di			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	LAKE RD			N/A	Shared Landing?	N/A			
Villen I				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
5	11	PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
The state of the s		R304.3.2		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
HARRIS TO THE REAL	🚯 (🔥 (👘	1004.3.2			X Walk 1 Direction	To S		X Walk 2 Direction	N/A
all the Alex	6			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A
Street 1 Name	MILHAVEN LN	1			X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A
Stop Condition-Street 1	StopSign			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
Stop Condition-Street 2	N/A				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
				11/5	Obstruction Type	11/4		Storm Grate/Utility Type	17/5
		Total Cost: \$	1600.00			N/A		eterni orato/ounty type	N/A
		10tal 000t. •	1000.00			17/4	Yes	Surface Condition? (G/P)	Good
							103		3000

