

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Nois Street, APPOR LOOP DD					Cross Street: CITY_PARK_DR				
Intersection ID: N/A	Main Str	Main Street: ARBOR_LOOP_DR			T_PARK_DK	Location:	SE			
ADA ID: B792753F8367	Ramp Ty	Ramp Type: Perp			Fail Overall C	o Severity Score:	12.5			
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
		Possible Solutions:	Compliance Description			Data Compliance Description			Data	
AL MART		Remove & Replace Entire Ramp.	N/A	A Ra	mp Length (in)	161.0	No	Ramp Slope (%)	8.5	
			Yes	Ra	mp Width (in)	70.0	Yes	Ramp XSlope (%)	0.5	
A A A A A A A A A A A A A A A A A A A	1 - NY		N/#	. Fla	are Type LT	N/A	N/A	Flare Type RT	N/A	
Are Produces			N/#	F la	are Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
b.m.d.+			N/A	Fla	are Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	·		N/#	Lar	nding Length (in)	N/A	N/A	DWS Provided?	N/A	
A A A	Set low	Surveyor Notes:	N/A	Lar	nding Width (in)	N/A	N/A	DWS Contrast?	N/A	
La Call	· har	N/A	N/A	Lar	nding Slope (%)	N/A	N/A	DWS Length (in)	N/A	
S S S S S S S S S S S S S S S S S S S	A A		N/A	Lar	nding X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	OOD DO		N/A	Lar	nding Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
it is an in	and the second s		N/A	Sha	ared Landing?	N/A				
		PROW/ADA:	N/A	Gu	Itter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	14 Martin	R304.2.2	N/#	Gu	ıtter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	1 mar		N/A	A Pai	inted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
			ΧV	Walk 1 Direction	To SW		X Walk 2 Direction	N/A		
1 - and had to			N/A	x x v	Valk 1 Width (in)	87.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	ARBOR LOOP DR			ХV	Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign			ХV	Valk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A		N/#	Ra	mp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A			Ro	ad Slope (%)	N/A	N/A	Clear Space?	N/A	
				Ro	ad X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
			N//	A Ang	y Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 1	850.00	Ob	struction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

