cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



									SW
Intersection ID: 10105	Main Street: FORESTBROOK_DR			Cross Street: TUCKASEEGEE_RD				Location:	
ADA ID: B8A46A935C7A Ramp Type: BlendTrans2			Initia	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	2	Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Remove & Replace Curb Ran	np With	N/A	Ramp Length (in)	116.0	Yes	BlendTrans Slope (%)	2.8
		Two New Directional Ramps	amps or	No	Ramp Width (in)	47.5	No	BlendTrans XSlope (%)	5.2
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
CALEEDEROOM				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
TUCIOLOGIA		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Martin Martin Bar		Not Found, R304.5.1, R304.5	.3	N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
THE AND THERE I				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name FORESTB	ROOK DR				X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	1.2		Clear Space?	N/A
					Road X Slope (%)	2.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.4