## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10034237 Main Street: PECAN_AV			Cross Street: N/A			Location:	SW	
ADA ID: B92144CE8AE0 Ramp Type: BlendTrans2		Initial Pass/F	nitial Pass/Fail: Pass Overall Compliance: No			o Severity Score:	7.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance				
	is is	Possible Solutions:	Comp	Compliance Description Data		Comp	Compliance Description	
		Remove & Replace Curb Ramp W	/ith N/A	Ramp Length (in)	71.0	Yes	BlendTrans Slope (%)	0.3
		Two New Directional Ramps or	Yes	Ramp Width (in)	68.0	No	BlendTrans XSlope (%)	3.4
		Equivalent. Remove & Replace Gutter.	N/A	Flare Type LT	None	N/A	Flare Type RT	None
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
			N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
A B	5 K	N/A	N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	25.0
			N/A	Landing X Slope (%)	N/A	No	DWS Full Width?	No
		PROW/ADA: Not Found, R304.5.3, R305.1.4, R305.2, R304.5.4	N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	24.0
			N/A	Shared Landing?	No		,	
			Yes	Gutter Ponding?		No	Gutter Slope (%)	8.3
			Yes	Gutter Lip Ht (in)		No	Gutter X Slope (%)	2.2
			N/A	Painted X Walk1?		N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name RAILROAD CROSSING				X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None			X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	N/A N/A
Street 2 Name	N/A		N/A	Ramp inside XWalk1?		N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A N/A		N/A	Road Slope (%)	0.5	IN/A	Clear Space?	Yes
Stop Condition-Street 2	N/A			• • • •		N/A		
			Vee	Road X Slope (%)	-		Clear Space to XWalk (in)	N/A
		Tatal Cast:	Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$ 39	50.00	Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

8.3