

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8861	Main Street: MELLOW_DR			Cross	Street:	N_TRYON_ST	Location:	NE		
ADA ID: BA1254BBF726	ID: BA1254BBF726 Ramp Type: Directional1			Initial	Initial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance										
	Possible Solutions:			Compliance Description Data			Compliance Description Data			
	and the second s	Remove & Replace Entir	e Ran	מו.	N/A	Ramp Length (in) 57.0	Yes	Grade Break?	Yes
				-P-	Yes	Ramp Width (in)	59.5	No	Grade Break Slope (%)	7.6
	The second				Yes	Ramp Slope (%)	7.3	No	Grade Break XSlope (%)	3.6
					Yes	Ramp XSlope (%	6) 1.3			
F FE					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	-				N/A	Flare Slope LT (9	%) 8.6	N/A	Flare Slope RT (%)	3.6
	1	Surveyor Notes:			N/A	Flare Traversable	e LT? No	N/A	Flare Traversable RT?	No
the second secon	the real	N/A			Yes	Landing Length ((in) 48.0	Yes	DWS Provided?	Yes
	-				Yes	Landing Width (ir	n) 59.5	Yes	DWS Contrast?	Yes
N_TRYON_ST					No	Landing Slope (%	%) 4.5	Yes	DWS Length (in)	24.0
	17				Yes	Landing X Slope	(%) 0.9	No	DWS Full Width?	No
the state of the second	1-1-1	PROW/ADA:			N/A	Landing Curb? (Y/N) N/A	Yes	DWS Offset LT (in)	25.0
	2 62.	Not Found, R304.2.2-Per	p, R30	04.3.2-	N/A	Shared Landing?	? No	No	DWS Offset RT (in)	3.0
		Para, R304.5.3, R305.1.4			No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	5.0
		R302.7, R302.7.2			No	Gutter Lip Ht (in)) 0.5	Yes	Gutter X Slope (%)	2.0
					N/A	Painted X Walk1	? No		Road Slope (%)	2.8
Street 1 Name M	IELLOW DR					X Walk 1 Directio	on To W		Road X Slope (%)	0.8
Stop Condition-Street 1	StopSign					X Walk 1 Width ((in) N/A		Clear Space?	Yes
Street 2 Name	N/A					X Walk 1 Slope ((%) 2.8	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A					X Walk 1 X Slope	e (%) 0.8	Yes	Storm Grate/Utility Hazard?	No
					N/A	Ramp inside XW	/alk1? N/A		Storm Grate/Utility Type	
					Yes	Any Obstructions	s? No			N/A
		Total Cost:	\$	1600.00		Obstruction Type	e	Yes	Surface Condition? (G/P)	Good
							N/A	No	Curb Slope (%)	13.0

