

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

6.0

1.9

N/A

N/A

N/A

Intersection ID: 51054 Main Street: MULBERRY\_CHURCH\_RD Cross Street: N/A Location: NW

ADA ID: BBC0720CB745 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Yes

Yes

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

Flare Traversable RT?

Flare Type RT

Data

48.0

47.0

N/A

N/A

N/A



Street 1 Name WESTPORT RD
Stop Condition-Street 2 YieldSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

PROW/ADA:
Not Found, R304.5.1

N

N

N

N

N

N

N

N

N

N

N

N

Total Cost:

\$ 1850.00

N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) Landing Slope (%) N/A N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A **Shared Landing?** N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A N/A N/A

N/A

No

N/A X Walk 1 Width (in)
X Walk 1 Slope (%)
X Walk 1 X Slope (%)

N/A Ramp inside XWalk1?
Road Slope (%)
Road X Slope (%)
N/A Any Obstructions?
Obstruction Type

N/

Compliance Description

Ramp Length (in)

Ramp Width (in)

|       |     | Tidio Tidio Cabio III I     |      |
|-------|-----|-----------------------------|------|
| N/A   | N/A | DWS Provided?               | N/A  |
| N/A   | N/A | DWS Contrast?               | N/A  |
| N/A   | N/A | DWS Length (in)             | N/A  |
| N/A   | N/A | DWS Full Width?             | N/A  |
| N/A   | N/A | DWS Offset (in)             | N/A  |
| N/A   |     |                             |      |
| N/A   | N/A | Gutter Slope (%)            | N/A  |
| N/A   | N/A | Gutter X Slope (%)          | N/A  |
| Yes   | N/A | Painted X Walk2?            | N/A  |
| To SW |     | X Walk 2 Direction          | N/A  |
| 118.0 | N/A | X Walk 2 Width (in)         | N/A  |
| 0.7   |     | X Walk 2 Slope (%)          | N/A  |
| 2.7   |     | X Walk 2 X Slope (%)        | N/A  |
| Yes   | N/A | Ramp inside XWalk2?         | N/A  |
| N/A   | N/A | Clear Space?                | N/A  |
| N/A   | N/A | Clear Space to XWalk (in)   | N/A  |
| N/A   | N/A | Storm Grate/Utility Hazard? | N/A  |
|       | l   | Storm Grate/Utility Type    |      |
| N/A   |     |                             | N/A  |
|       | Yes | Surface Condition? (G/P)    | Good |
|       |     |                             |      |
|       |     |                             |      |
|       |     |                             |      |





