## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10011612 Main Street: UNIVERSITY_CITY_BV					Street:	N/A	Location:	NE		
ADA ID: BC250D82BB2B Ramp Type: BlendTrans1					Pass/Fa	ail: Pass Overal	o Severity Score:	7.5		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Comp	liance Description	Description Data		Compliance Description	
		Remove & Replace Cur	b Ram	with	N/A	Ramp Length (in)	98.0	Yes	BlendTrans Slope (%)	4.4
		Two New Directional Ra			Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	0.9
		Equivalent.	•		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
					N/A	Flare Slope LT (%)	2.9	N/A	Flare Slope RT (%)	4.8
					N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
		4			Yes	Landing Length (in)	72.0	Yes	DWS Provided?	Yes
		Surveyor Notes:			Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
L L L		N/A			Yes	Landing Slope (%)	1.4	Yes	DWS Length (in)	24.0
		176			Yes	Landing X Slope (%)	0.8	Yes	DWS Full Width?	Yes
UNIVERSITY					N/A	Landing Curb? (Y/N)	No		DWS Offset (in)	3.5
					N/A	Shared Landing?	No			
ANVIN		PROW/ADA:			No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	4.2
ALL	6.		127 D	20272	No	Gutter Lip Ht (in)	0.5	Yes	Gutter X Slope (%)	0.2
Not Found, R305.2, R302.7, R302.7.2				302.7.2	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					N/A	X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	Bas BET LOT					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name UNIVERSITY CITY BV						4.3			N/A N/A	
						X Walk 1 Slope (%)			X Walk 2 Slope (%)	
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A					Road Slope (%)	0.9		Clear Space?	Yes
						Road X Slope (%)	4.3	N/A	Clear Space to XWalk (in)	N/A
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

16.8