

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 20523 Main Street: SOUTH_BV Cross Street: WISTERIA_DR Location: SE

ADA ID: BC9A49AB31F7 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 37.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

WISTERIA DR StopSign SOUTH BV None

Possible Solution	
Possible Solutions:	9
Remove & Replace Curb Ramp With	ı
Two New Directional Ramps or	•
Equivalent.	ı
	ı
	ı
	ı
Surveyor Notes:	ı
N/A	ı
	ı
	ı
	ı
PROW/ADA:	ı
Not Found, R304.2.2, R304.5.3	ı
	I

Total Cost: \$ 3200.00

	Field Measure	ements/C	unipo	Hent Comphance	
Compliance Description		Data	Compliance Description		Data
N/A	Ramp Length (in)	65.0	No	Ramp Slope (%)	9.2
Yes	Ramp Width (in)	49.0	No	Ramp XSlope (%)	7.6
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To N		X Walk 2 Direction	To W
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	6.8		X Walk 2 Slope (%)	9.0
	X Walk 1 X Slope (%)	6.3		X Walk 2 X Slope (%)	3.0
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	4.2	N/A	Clear Space?	N/A
	Road X Slope (%)	7.5	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good





