

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 22011 Main Street: SOUTH\_BV Cross Street: HILL\_RD Location: SE **Overall Compliance: No** Severity Score: 13.75 ADA ID: BCB645694527 Ramp Type: Para Initial Pass/Fail: Fail

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name	SOUTH BV
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

-055ible Solution	
Possible Solutions:	С
Remove & Replace Entire Ramp.	
·	Y
	N
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
R304.3.2, R304.5.3	N
	N

Total Cost:	\$ 1600.00

Field Measurements/Component Compliance  Compliance Description Data Compliance Description Data							
N/A	Ramp Length LT (in)	58.0	N/A	Ramp Length RT (in)	58.0		
Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	71.0		
No	Ramp Slope LT (%)	9.3	No	Ramp Slope RT (%)	9.0		
No	Ramp XSlope LT (%)	2.9	No	Ramp XSlope RT (%)	2.1		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	<b>3</b> . ( )	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing X Slope (%)						
	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A	NI/A	Otan Olana (0/ )	NI/A		
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
			N/A	Curb Slope (%)	7.0		





