cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13073	Main Street: FARMVIEW_RD			Cross Street: WOODLEAF_RD				Location:	Ν	
ADA ID: BDBD8EE15266	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: N			nce: N	o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:						Compliance Description		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	60.0	Yes	BlendTrans Slope (%)	Data 4.5	
		Two New Directional Ramps or	· · · · · ·	No	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	1.3	
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
No the second		10/4		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
and a state of the	1			N/A	Shared Landing?	N/A				
	and the	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	Not i Guild, 1304.5.1		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name FARMVIEW RD					X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	0.0 N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A			N/A	Road Slope (%)	0.8		Clear Space?	N/A	
					Road X Slope (%)	2.6	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	2.0 N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00	11/5	Obstruction Type			Storm Grate/Utility Type	197	
		φ	200.00			N/A		Stand Grate/Guilty Type	N/A	
						13/A			11/1	





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.1