## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47977 Main Str		reet: AVALY_LN	Cross Street: SPRINGS_MILL_RD					Location:	SE
ADA ID: C016E4124C25 Ramp T		ype: BlendTrans1	BlendTrans1 Initial Pass/Fail: Fail		ail: Fail Overall C	Overall Compliance: No		o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:					liance Description	Data	
	SPRINCES MILL RD	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	71.0	Yes	BlendTrans Slope (%)	4.1
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	41.0	Yes	BlendTrans XSlope (%)	1.5
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
- B mai				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
6				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		CURB GAP 1.5		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Mit I		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Contract (Contraction)	The second				X Walk 1 Direction	To N		X Walk 2 Direction	To W
And the base	the second se				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	SPRING MILL RD				X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	3.4
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	3.4
Street 2 Name	AVALY LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	1.3		Clear Space?	N/A
					Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

7.9