

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10004304 Main Street: MULLAN_LN Cross Street: REALTA_DR Location: SE ADA ID: C089BC50A90A Ramp Type: BlendTrans1 Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 10

Codes/Mitigation Info/P

Field Measurements/Component Compliance



REALTA DR Street 1 Name Stop Condition-Street 1 None Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solution	
Possible Solutions:	<u>c</u>
Remove & Replace Curb Ramp With	N
Two New Directional Ramps or	N
Equivalent.	N
	N
	N
	N
Surveyor Notes:	N
CURB LIP 1.0	N
	N
	N
	N
PROW/ADA:	N
Not Found, R304.5.1	N
	N

Surveyor Notes:		N/A
CURB LIP 1.0		N/A
		N/A
		N/A
		N/A
PROW/ADA:		N/A
Not Found, R304.5.1		N/A
		N/A
		N/A
		N/A
Total Cost:	\$ 3200.00	



Field Measurements/Component Compliance							
Compliance Description Dat			Comp	liance Description	Data		
N/A	Ramp Length (in)	95.5	Yes	BlendTrans Slope (%)	4.0		
No	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	2.6		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A		
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	5.2		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	5.2		Clear Space?	N/A		
	Road X Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
			No	Curb Slope (%)	5.1		