cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 11345	ersection ID: 11345 Main Street: W_MARTIN_LUTHER_KING_JRCB06s Street: WALNUT_AV								Location:	S
ADA ID: C0A990F3EDF1	Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance:				o Severity Score:	26.25
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description		Data	Data Compliance Description		Data
A CARLON AND AND AND AND AND AND AND AND AND AN	We do a	Remove & Replace En	tire Ram	р.	N/A	Ramp Length (in)	29.5	No	Ramp Slope (%)	12.2
	de			•	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.7
12 1 1 1 M	M. Can				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Starl.				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
1000	· ·				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	A States	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	and the second	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
5	ST				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
The American					N/A	Shared Landing?	N/A			
A PIE STAN	AN AN	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2, F	R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the second of the		,			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
A A A A A A A A A A A A A A A A A A A	1 × 10	5				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
AND AN SAL SAL					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	W 2ND ST	_				X Walk 1 Slope (%)	4.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

