

Access Compliance Report Public Rights-of-Way (Curb Ramps)



									NUAZ
Intersection ID: 50607	Main Street: DENBUR_DR			Cross Street: STREAM_ORCHID_LN				Location:	NW
ADA ID: C0FEE4BFD330	DA ID: C0FEE4BFD330 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	51	Possible Solutions:		Compliance Description Date			ta Compliance Description		Data
		Remove & Replace Entire Ra	mp.	N/A	Ramp Length (in)	48.5	Yes	Ramp Slope (%)	8.3
			•	No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	3.3
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
the second s	* Statistical adult of the			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
().) \) ·	11			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	****	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
t.	<u>6</u>	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
DENBUR_DR				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second the	de la companya de la			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the second second second second	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			N/A	Shared Landing?	N/A			
and the second second	and the state	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	S ST ST			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
and the second second					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	DENBUR DR				X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

