

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

56.0

70.0

5.7

2.2

2.7

3.7

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 14111 Main Street: CENTRAL_AV Cross Street: LANSDALE_DR Location: NW

ADA ID: C1E21D6A919E Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 61.25

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

Yes

No

No

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

No

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

41.0

71.0

14.0

2.5

128.0

31.5

N/A

N/A

N/A

N/A

N/A

N/A

N/A



Street 1 Name
StopSign
Stop Condition-Street 1
LANDSDALE DR
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.5.3, R304.3.2



Total Cost:



1800.00

,	,		` ,	
Shared Landing?	N/A			
Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Painted X Walk1?	No No	N/A	Painted X Walk2?	N/A
X Walk 1 Direction	n To E		X Walk 2 Direction	N/A
X Walk 1 Width (i	n) N/A		X Walk 2 Width (in)	N/A
X Walk 1 Slope (9	%) 1.3		X Walk 2 Slope (%)	N/A
X Walk 1 X Slope	(%) 3.0		X Walk 2 X Slope (%)	N/A
Ramp inside XWa	alk1? N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	N/A		Clear Space?	N/A
Road X Slope (%) N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstruction?	N/A
The state of the s			Obstruction Type	
The state of the s				N/A
		N/A	Storm Grate/Utility Hazard?	N/A
		l	Storm Grate/Utility Type	
				N/A
		Yes	Surface Condition? (G/P)	Good
			Curb Slope (%)	25.7