





Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: N/A	Main Street: SCOFIELD_RD	Cross Street: WINTERCREST_LN	Location: SW
ADA ID: C27A8BA6E5C3	Ramp Type: Combination2	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Possible Solutions:			Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.			N/A	Ramp Length LT (in)	60.0	N/A	Ramp Length RT (in)	N/A
				Yes	Ramp Width LT (in)	58.0	N/A	Ramp Width RT (in)	N/A
				No	Ramp Slope LT (%)	8.7	N/A	Ramp Slope RT (%)	N/A
				Yes	Ramp XSlope LT (%)	1.1	N/A	Ramp XSlope RT (%)	N/A
				N/A	Ramp Length (in)	36.0	Yes	Ramp Slope (%)	7.2
				Yes	Ramp Width (in)	75.0	No	Ramp XSlope (%)	4.3
	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
PROW/ADA:				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Not Found, R304.5.3, R304.3.2				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	4.9		X Walk 2 Slope (%)	N/A
					X Walk 1 X Slope (%)	3.9		X Walk 2 X Slope (%)	N/A
				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	N/A		Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
							N/A	Any Obstruction?	N/A
								Obstruction Type	N/A
							N/A	Storm Grate/Utility Hazard?	N/A
								Storm Grate/Utility Type	N/A
									N/A
							Yes	Surface Condition? (G/P)	Good
								Curb Slope (%)	11.1
<div><div></div></div>									