

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48374Main Street: REDBUD_STCross Street: TATE_STLocation:NEADA ID: C2D3FE5C085BRamp Type: ParaInitial Pass/Fail: PassOverall Compliance: NoSeverity Score: 15.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name	REDBUD ST
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solutions:

Remove & Replace Entire Ramp.
Remove & Replace Gutter.

Surveyor Notes:

LT RP < 5%

PROW/ADA:

Not Found, R304.5.3, R304.2.1,
R305, R304.5.4

otal Cost:	œ.	2350.00
olai Cost.	20	∠აⴢ∪.∪∪

Comp	liance Description	Data	Comp	liance Description	Data
N/A	Ramp Length LT (in)	60.5	N/A	Ramp Length RT (in)	62.5
Yes	Ramp Width LT (in)	60.5	Yes	Ramp Width RT (in)	60.0
Yes	Ramp Slope LT (%)	2.7	Yes	Ramp Slope RT (%)	7.9
No	Ramp XSlope LT (%)	2.1	Yes	Ramp XSlope RT (%)	1.7
Yes	Landing Length (in)	60.0	No	DWS Provided?	No
No	Landing Width (in)	38.0	N/A	DWS Contrast?	No
Yes	Landing Slope (%)	1.5	N/A	DWS Length (in)	N/A
Yes	Landing X Slope (%)	2.3	N/A	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	No	Gutter Slope (%)	10.0
Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	4.2
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			Replace Curb Siloppe (%)		
*					





