cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23090	Main Street: CHALYCE_LN			Cross	Street:	LYNBRIDGE_DR	Location:	NW		
ADA ID: C32D6D83A2D8	Ramp Type: BlendTrans2			Initial	Pass/Fa	ail: Fail Overall C	o Severity Score:	10		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description			Data Compliance Description		
		Remove & Replace Cur	Ram	p With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	4.2
		Two New Directional Ra			No	Ramp Width (in)	39.5	No	BlendTrans XSlope (%)	3.9
		Equivalent.	•		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Surveyor Notes:			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
LYNERIDCE DR. C.					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		1071			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
in the second second	-			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R	304 5	3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		004.0.	•	N/A	Painted X Walk1?	No		Painted X Walk2?	No	
The second second					X Walk 1 Direction	To S		X Walk 2 Direction	To E	
						X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	LYNBRIDGE DR	-				X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	3.9
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	6.4		X Walk 2 X Slope (%)	1.7
Street 2 Name	CHALYCE LN				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign					Road Slope (%)	1.7		Clear Space?	N/A
						Road X Slope (%)	4.2	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
			Ŧ				N/A			N/A
							17/4			11/2







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

6.9