cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11941	Main Street: BELMONT AV			Cross Street: N_ALEXANDER_ST				Location:	Ν	
ADA ID: C336AD6A4013	Ramp Type: BlendTrans2			Initial Pass/Fail: Fail Overall Complia					10	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
Possible Solutions:				- · · · ·						
		6	\ A /:41-	N/A Ramp Length (in)		72.0 Yes BlendTrans Slope (%)		Data 3.5		
		Remove & Replace Curb Ramp Two New Directional Ramps or	with	N/A No	Ramp Width (in)	47.5		BlendTrans XSlope (%)	3.5 4.2	
		Equivalent.		N/A		47.5 N/A	N/A	,	4.2 N/A	
					Flare Type LT			Flare Type RT		
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
the state of the s		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
S S S				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
A CONTRACTOR OF A CONTRACTOR OFTA CONTRACTOR O		8		N/A	Shared Landing?	N/A				
(B) (B)		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
a state of the sta	1 100	R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	1 6	8			X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
And the second second		1			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	BELMONT AV	-			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A				Road Slope (%)	2.8		Clear Space?	N/A	
					Road X Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 3	3200.00	11/5	Obstruction Type			Storm Grate/Utility Type	197	
		φ	200.00		Obstruction Type	NI/A		Gorm Grate/Otility Type	N/A	
						N/A	1		N/A	







Yes

N/A

Surface Condition? (G/P)

Curb Slope (%)

Good

3.2