


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10037305	Main Street: SARDIS_RD	Cross Street: N/A	Location: SW
ADA ID: C37A9EC342A3	Ramp Type: Combination1Diag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 0	

Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Possible Solutions:			Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.			N/A	Ramp Length LT (in)	46.0	N/A	Ramp Length RT (in)	36.0
				Yes	Ramp Width LT (in)	58.0	Yes	Ramp Width RT (in)	60.0
				Yes	Ramp Slope LT (%)	3.4	Yes	Ramp Slope RT (%)	6.8
				Yes	Ramp XSlope LT (%)	1.8	Yes	Ramp XSlope RT (%)	0.8
				N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	6.4
				No	Ramp Width (in)	37.0	No	Ramp XSlope (%)	3.0
	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	LT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
PROW/ADA:			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
Not Found, R304.5.1, R304.5.3			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
				X Walk 1 Direction	To NW		X Walk 2 Direction	To NW	
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
				X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	4.9	
				X Walk 1 X Slope (%)	4.3		X Walk 2 X Slope (%)	0.3	
Total Cost:			\$ 3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	2.6		Clear Space?	N/A
					Road X Slope (%)	3.3	N/A	Clear Space to XWalk (in)	N/A
						N/A	Any Obstruction?	N/A	
							Obstruction Type	N/A	
						N/A	Storm Grate/Utility Hazard?	N/A	
							Storm Grate/Utility Type	N/A	
						Yes	Surface Condition? (G/P)	Good	
							Curb Slope (%)	6.9	
								</	

