


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 12224	Main Street: MILLERTON_AV	Cross Street: FLEETWOOD_DR	Location:	N
ADA ID: C44A208714B9	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 8.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance											
	Possible Solutions:		Compliance			Description			Data					
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)		60.0		Yes	Ramp Slope (%)		8.2			
			No	Ramp Width (in)		46.5		Yes	Ramp XSlope (%)		0.6			
			N/A	Flare Type LT		N/A		N/A	Flare Type RT		N/A			
			N/A	Flare Slope LT (%)		N/A		N/A	Flare Slope RT (%)		N/A			
			N/A	Flare Traversable LT?		N/A		N/A	Flare Traversable RT?		N/A			
			N/A	Landing Length (in)		N/A		N/A	DWS Provided?		N/A			
			N/A	Landing Width (in)		N/A		N/A	DWS Contrast?		N/A			
			N/A	Landing Slope (%)		N/A		N/A	DWS Length (in)		N/A			
			N/A	Landing X Slope (%)		N/A		N/A	DWS Full Width?		N/A			
Surveyor Notes:		N/A			N/A			DWS Offset (in)			N/A			
PROW/ADA:		Not Found, R304.5.1			N/A									
					N/A			Gutter Ponding?			N/A			
					N/A			Gutter Lip Ht (in)			N/A			
					N/A			Painted X Walk1?			No			
					To SW			X Walk 2 Direction			N/A			
		N/A			N/A			X Walk 2 Width (in)			N/A			
					0.5			X Walk 2 Slope (%)			N/A			
					0.3			X Walk 2 X Slope (%)			N/A			
		N/A			N/A			Ramp inside XWalk2?			N/A			
					N/A			Clear Space?			N/A			
					N/A			Clear Space to XWalk (in)			N/A			
		N/A			N/A			Storm Grate/Utility Hazard?			N/A			
								Storm Grate/Utility Type						
					N/A						N/A			
								Yes			Surface Condition? (G/P)		Good	

