


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                       |                        |                         |                        |
|-----------------------|------------------------|-------------------------|------------------------|
| Intersection ID: 9973 | Main Street: CAMPUS_ST | Cross Street: FRENCH_ST | Location: NW           |
| ADA ID: C4BAB5946E40  | Ramp Type: BlendTrans1 | Initial Pass/Fail: Fail | Overall Compliance: No |
|                       |                        | Severity Score: 12.5    |                        |

| Codes/Mitigation Info/Possible Solution  |  |  | Field Measurements/Component Compliance |                       |      |            |                             |      |
|--|--|--|---|-----------------------|------|------------|-----------------------------|------|
|  | Possible Solutions:  |  | Compliance                              | Description           | Data | Compliance | Description                 | Data |
|  | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. |  | N/A                                     | Ramp Length (in)      | 64.0 | Yes        | BlendTrans Slope (%)        | 2.5  |
|  |  |  | Yes                                     | Ramp Width (in)       | 48.0 | No         | BlendTrans XSlope (%)       | 6.0  |
|  |  |  | N/A                                     | Flare Type LT         | N/A  | N/A        | Flare Type RT               | N/A  |
|  |  |  | N/A                                     | Flare Slope LT (%)    | N/A  | N/A        | Flare Slope RT (%)          | N/A  |
|  |  |  | N/A                                     | Flare Traversable LT? | N/A  | N/A        | Flare Traversable RT?       | N/A  |
|  |  |  | N/A                                     | Landing Length (in)   | N/A  | N/A        | DWS Provided?               | N/A  |
|  |  |  | N/A                                     | Landing Width (in)    | N/A  | N/A        | DWS Contrast?               | N/A  |
|  |  |  | N/A                                     | Landing Slope (%)     | N/A  | N/A        | DWS Length (in)             | N/A  |
|  |  |  | N/A                                     | Landing X Slope (%)   | N/A  | N/A        | DWS Full Width?             | N/A  |
| Surveyor Notes:  |  |  | N/A                                     | Landing Curb? (Y/N)   | N/A  | N/A        | DWS Offset (in)             | N/A  |
| PROW/ADA:  |  |  | N/A                                     | Shared Landing?       | N/A  |            |                             |      |
| Not Found, R304.5.3  |  |  | N/A                                     | Gutter Ponding?       | N/A  | N/A        | Gutter Slope (%)            | N/A  |
|  |  |  | N/A                                     | Gutter Lip Ht (in)    | 2.5  | N/A        | Gutter X Slope (%)          | N/A  |
|  |  |  | N/A                                     | Painted X Walk1?      | No   | N/A        | Painted X Walk2?            | No   |
|  |  |  |   | X Walk 1 Direction    | To S |            | X Walk 2 Direction          | To E |
|  |  |  |   | X Walk 1 Width (in)   | N/A  |            | X Walk 2 Width (in)         | N/A  |
|  |  |  |   | X Walk 1 Slope (%)    | 1.2  |            | X Walk 2 Slope (%)          | 6.8  |
|  |  |  |   | X Walk 1 X Slope (%)  | 6.1  |            | X Walk 2 X Slope (%)        | 0.4  |
|  |  |  | N/A                                     | Ramp inside XWalk1?   | N/A  | N/A        | Ramp inside XWalk2?         | N/A  |
|  |  |  |   | Road Slope (%)        | 5.6  |            | Clear Space?                | N/A  |
|  |  |  |   | Road X Slope (%)      | 4.0  | N/A        | Clear Space to XWalk (in)   | N/A  |
|  |  |  | N/A                                     | Any Obstructions?     | N/A  | N/A        | Storm Grate/Utility Hazard? | N/A  |
|  |  |  |   | Obstruction Type      |      |            | Storm Grate/Utility Type    |      |
|  |  |  |   |                       | N/A  |            |                             | N/A  |
|  |  |  |   |                       |      | Yes        | Surface Condition? (G/P)    | Good |
|  |  |  |   |                       |      | No         | Curb Slope (%)              | 22.3 |
|  |  |  |   |                       |      |            |                             |      |
|  |  |  |   |                       |      |            |                             |      |
|  |  |  |   |                       |      |            |                             |      |

