

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13228	Main Str	eet: CENTRAL_AV	Cross Str	reet:	LANDIS_AV	Location:	NE		
ADA ID: C6FC296BA307	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Possible Solutions:						liance Description	Data	
		Remove & Replace Entire Ramp	. N	I/A	Ramp Length (in)	58.0	Yes	Ramp Slope (%)	5.0
	Same 8			lo	Ramp Width (in)	40.0	No	Ramp XSlope (%)	2.4
En la			N	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
ton to	4		N	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Contraction of the		N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	-	Surveyor Notes:	N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E E	<mark>હ્</mark> ર	N/A	N	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
GENTRAL_AV	E		N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	H		N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the second secon	the state		N	I/A	Shared Landing?	N/A			
		PROW/ADA:	N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	all all and	Not Found, R304.5.1, R304.5.3	N	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Adde when		N	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
THE AND MERCEN	144 30.00				X Walk 1 Direction	To W		X Walk 2 Direction	N/A
			N	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	LANDIS AV	-			X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		Ν	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A



Good

