

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

42.5

59.0

10.6

4.5

7.2

4.0

N/A

No

N/A

5.2

4.9

N/A

N/A

To NE

Intersection ID: 47457 Main Street: STEELE CREEK RD **Cross Street: WINGED TEAL RD** Location: NW **Overall Compliance: No Severity Score:** ADA ID: C8096E34F16A Ramp Type: Combination1Diag Initial Pass/Fail: Fail 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

Data

42.0

59.0

3.2 No

4.4

83.0

46.5

N/A

No

N/A

1.2

3.3

N/A

4.5

To SE



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

StopSign WINGED TEAL RD None STEELE CREEK RD Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: LT RP < 5% PROW/ADA Not Found, R304.5.1, R304.5.3, R304.3.2

Total Cost:

N/A Ramp Length LT (in) Yes Ramp Width LT (in) Yes Ramp Slope LT (%) Ramp XSlope LT (%) No N/A Ramp Length (in) No Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction

N/A

Compliance Description

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)



3200.00

Road X Slope (%) 1.9 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 10.6 Curb Slope (%)



