

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44446	tersection ID: 44446 Main Street: REAMES_RD			Cross Street: PRESTBURY_BV					NE
ADA ID: C9737237770D	7770D Ramp Type: BlendTrans1		Initial Pas	ss/Fa	ail: Pass Overall	o Severity Score:	0.25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:	<u>c</u>	Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp V	Vith N	I/A	Ramp Length (in)	100.0	Yes	BlendTrans Slope (%)	4.7
10 10 10 10 10		Two New Directional Ramps or		'es	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	4.4
		Equivalent.	Ν	I/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
			Ν	I/A	Flare Slope LT (%)	4.4	N/A	Flare Slope RT (%)	5.3
allow a			N	I/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
			۲	'es	Landing Length (in)	51.0	Yes	DWS Provided?	Yes
		Surveyor Notes:	۲	'es	Landing Width (in)	51.0	Yes	DWS Contrast?	Yes
		N/A	Y	'es	Landing Slope (%)	1.6	Yes	DWS Length (in)	24.0
			Ν	lo	Landing X Slope (%)	4.6	Yes	DWS Full Width?	Yes
PRESTBUT	NY_EV			I/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	2.0
				I/A	Shared Landing?	No		()	
5		PROW/ADA:		'es	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.0
6		R304.5.3		'es	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.3
		K304.5.5		1/A	Painted X Walk1?	No		Painted X Walk2?	No
			•		X Walk 1 Direction	To W		X Walk 2 Direction	To S
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	REAMES RD				X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	1.1
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	1.1
Stop Condition-Street 1	PRESTBURY BV			I/A	,	2.3 N/A	N/A	,	N/A
			r	I/A	Ramp inside XWalk1?		N/A	Ramp inside XWalk2?	
Stop Condition-Street 2	StopSign				Road Slope (%)	0.6		Clear Space?	Yes
					Road X Slope (%)	0.7		Clear Space to XWalk (in)	N/A
				'es	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

N/A

Surface Condition? (G/P)

Curb Slope (%)

Good

3.4