

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-		-						
Intersection ID: 7979	Main Street: EAGLE_PEAK_DR			Street:	DAVID_AV	Location:	N/A			
ADA ID: CA9878095A3F	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:					Compliance Description Data			
	Cart -	Remove & Replace Entire Ram	D .	N/A	Ramp Length (in)	49.0	Yes	Ramp Slope (%)	7.2	
	the set	· · · · · · · · · · · · · · · · · · ·	P.	No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	2.8	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Process Process	1			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		9		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	a to contra			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	<u>ь</u>			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
B.A.	¢ 10.			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	1			N/A	Shared Landing?	N/A				
	1 1	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
The state of the state	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A		
TALLA LAND	1		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
TABLE ANTON				X Walk 1 Direction	To S		X Walk 2 Direction	N/A		
and the second			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name	DAVID AV	_			X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	3.0	N/A	Clear Space?	N/A	
					Road X Slope (%)	3.4	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

