

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



					-						
Intersection ID: N/A	Main Street: S_CALDWELL_ST			Cross	Street:	E_3RD_ST	Location:	SE			
ADA ID: CAACA783D99E	Ramp Type: Directional1			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:				Compliance Description		Data Compliance Description		Data	
		Remove & Replace Entir	e Ran	מו.	N/A	Ramp Length (in)	110.0	N/A	Grade Break?	N/A	
	M.	Remove & Replace Gutte		F.	Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0	
6.6	10/	-			No	Ramp Slope (%)	10.3	N/A	Grade Break XSlope (%)	0.0	
					Yes	Ramp XSlope (%)	4.9				
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
E. S. E.	14	Surveyor Notes:			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A			No	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
6.					No	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	A 1 3 1 1				No	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
A State Contract	A.	PROW/ADA:			No	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	A STATE OF A				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	1 6	R304.2.2, R304.2.1, R304	erp.	N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
		R304.3.2-Para, R304.5.3,	• •	Yes	Gutter Ponding?	0.0	No	Gutter Slope (%)	N/A		
		R304.5.4			No	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	N/A	
	10				N/A	Painted X Walk1?	Yes		Road Slope (%)	4.0	
Street 1 Name E	3RD ST					X Walk 1 Direction	To NE		Road X Slope (%)	7.3	
Stop Condition-Street 1	Signal					X Walk 1 Width (in)	120.0		Clear Space?	N/A	
Street 2 Name	N/A					X Walk 1 Slope (%)	4.0	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	7.3	Yes	Storm Grate/Utility Hazard?	N/A	
					Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type		
					Yes	Any Obstructions?	N/A			N/A	
		Total Cost:	\$	2350.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
							N/A	N/A	Curb Slope (%)	5.8	

