cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10026799 Main Street: FOREST_POINT_BV Cross Street: N/A								Location:	NW
ADA ID: CAED8BA48069 Ramp Type: PerpDiag Ir			Initial F	tial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data C			Comp	Compliance Description Da	
		Remove & Replace Curb Ramp	Vith	N/A	Ramp Length (in)	112.0	Yes	Ramp Slope (%)	5.8
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.2
the state of the state		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	<u>E.</u>			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
The The	A	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
t.		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	or and	14		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A CARACTER AND A CARACTER ANTE ANO CARACTER ANTE ANO CARACTER ANTE ANO CARACTER ANTE ANTE ANTE ANTE ANTE ANTE ANTE ANTE	alle alle			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A A A A A A A A A A A A A A A A A A A				N/A	Shared Landing?	N/A			
	and the second	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
the second second	N. S. A. M. Land	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	SE AL			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
MA KNOW		<u>.</u>			X Walk 1 Direction	To S		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	FOREST POINT BV				X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	4.2
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	5.7		X Walk 2 X Slope (%)	2.3
Street 2 Name	ENTRANCE			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	3.8	N/A	Clear Space?	N/A
					Road X Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
4									

Yes Surface Condition? (G/P)

Good

