

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

30.0

60.5

6.3

4.0

6.3

8.0

N/A

No

To W

N/A

1.0

0.3

N/A

N/A

Intersection ID: N/A Main Street: LOG CABIN RD **Cross Street: TOM HUNTER RD** Location: SE **Overall Compliance: No Severity Score:** 0 ADA ID: CB461C0ABB06 Ramp Type: Combination2Diag Initial Pass/Fail: Fail

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

0.1

1.1

N/A

0.9

N/A

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

Ramp XSlope RT (%)



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

None TOM HUNTER RD StopSign LOG CABIN RD Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3

Total Cost:

Compliance Description Data Compliance Description N/A N/A Ramp Length LT (in) 31.0 Yes Ramp Width LT (in) 60.0 Yes Yes Ramp Slope LT (%) 1.3 Yes Ramp XSlope LT (%) 2.5 No No N/A Ramp Length (in) 47.0 Yes 35.5 Yes No Ramp Width (in) N/A Flare Type LT N/A N/A N/A N/A Flare Slope LT (%) N/A N/A Flare Traversable LT? N/A N/A N/A Landing Length (in) N/A N/A N/A N/A N/A Landing Width (in) N/A Landing Slope (%) N/A N/A N/A Landing X Slope (%) N/A N/A N/A Landing Curb? (Y/N) N/A N/A N/A Shared Landing? N/A N/A **Gutter Ponding?** N/A N/A N/A N/A Gutter Lip Ht (in) N/A N/A N/A Painted X Walk1? No To N X Walk 1 Direction X Walk 1 Width (in) N/A

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)







N/A

3200.00

1.5	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstruction?	N/A
		Obstruction Type	
			N/A
	N/A	Storm Grate/Utility Hazard?	N/A
		Storm Grate/Utility Type	
			N/A
	Yes	Surface Condition? (G/P)	Good
		Curb Slope (%)	19.3