## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 52906	tion ID: 52906 Main Street: JOHNSTON_RD			Cross	Street:	CLEMS_CROSSING_	Location:	SE			
ADA ID: CC236D25C25I	25E Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	1.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:		Compliance D		liance Description	scription Data		Compliance Description		
	o K	Remove & Replace Curb R Two New Directional Ramp Equivalent.	Ramp W	Vith	N/A	Ramp Length (in)	72.0	Yes	BlendTrans Slope (%)	1.1	
			•		Yes	Ramp Width (in)	71.0	No	BlendTrans XSlope (%)	2.2	
			•		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		1			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
Son	FY				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	6 ·	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
PROW/ADA: Not Found, R304.5.3					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
					N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
					N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
						X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
						X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name CLEMS CROSSING DR					X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A		
Stop Condition-Street 1	StopSign					X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A					Road Slope (%)	1.4		Clear Space?	N/A	
						Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$ 32	00.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	
								1			







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

12.6