

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3246 Main Street: OLD TIMBER RD Cross Street: SADDLE PACE LN Location: SW							
Intersection ID: 3246 M	Main Street: OLD_TIMBER_RD		Cross Street: SADDLE_PACE_LN			SW	
ADA ID: CC7C48D73622 R	3622 Ramp Type: BlendTrans1		ail: Fail Overall (No Severity Score:	18.75		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance				
	Possible Solutions:	Com	Compliance Description Data		Compliance Description Data		
	Remove & Replace Curb Ramp \	Nith N/A	Ramp Length (in)	52.5 Yes	BlendTrans Slope (%)	3.8	
	Two New Directional Ramps or	No	Ramp Width (in)	35.0 No	BlendTrans XSlope (%)	2.5	
	Equivalent.	N/A	Flare Type LT	N/A N/A	Flare Type RT	N/A	
		N/A	Flare Slope LT (%)	N/A N/A	Flare Slope RT (%)	N/A	
	14	N/A	Flare Traversable LT?	N/A N/A	Flare Traversable RT?	N/A	
	1 p	N/A	Landing Length (in)	N/A N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/A	Landing Width (in)	N/A N/A	DWS Contrast?	N/A	
	N/A	N/A	Landing Slope (%)	N/A N/A	DWS Length (in)	N/A	
	1 The second second	N/A	Landing X Slope (%)	N/A N/A	DWS Full Width?	N/A	
		N/A	Landing Curb? (Y/N)	N/A N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A			
	PROW/ADA:	N/A	Gutter Ponding?	N/A N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1, R304.5.3	N/A	Gutter Lip Ht (in)	N/A N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	No N/A	Painted X Walk2?	N/A	
			X Walk 1 Direction	To SE	X Walk 2 Direction	N/A	
	* 8		X Walk 1 Width (in)	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name SADDLE PA	CE LN		X Walk 1 Slope (%)	8.5	X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1 Sto	opSign		X Walk 1 X Slope (%)	1.9	X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A	N/A	Ramp inside XWalk1?	N/A N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A		Road Slope (%)	1.9	Clear Space?	N/A	
			Road X Slope (%)	8.5 N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 3	200.00	Obstruction Type		Storm Grate/Utility Type		
				N/A		N/A	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

7.8