cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3845 Main Street: ZIEGLER_LN Cross Street: N/A							Location:	SE	
ADA ID: CCD22E674AC5 Ramp Type: BlendTrans1			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	17.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data	ata Compliance Description		Data
to the total of		Remove & Replace Curb Ram	p With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	0.5
		Two New Directional Ramps of	or	No	Ramp Width (in)	32.0	Yes	BlendTrans XSlope (%)	1.4
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Ellas 6.				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	11-11			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	- March	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Friting 1		,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	ZIEGLER LN				X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	2.2
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	1.4
Street 2 Name	DERVISH LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	0.2		Clear Space?	N/A
					Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.1